

Phase 5 — Block 7 Overview

Block 7 prepares technicians to earn their EPA 608 Certification by building an understanding of refrigerant regulations, safe refrigerant handling practices, and certification requirements. Through guided learning resources, practice exams, and final

certification, the Technician will develop the knowledge required to safely service refrigeration systems while remaining compliant with EPA regulations. Once the exam is successfully completed, be sure to upload your certification to the DRW platform.

Block Completion Requirements

Access all Absorb resources through the DRW platform and complete each of the four EPA 608 Practice Tests before proceeding to the final certification exam. After successfully passing the EPA 608 Certification Exam, return to the DRW platform and upload a copy of your EPA Certification Card for Supervisor verification and documentation.



1. Review all Absorb resources



2. Articulate: Take and pass all linked EPA Practice Exams



3. Pass EPA 608 Certification Exam and upload your certification card

Absorb Resources

Refer to the DRW Learning Block online for the complete list of assigned resources for this block. Topics to review include:

ASSIGNED VIDEOS

- EPA 608 Core Prep
- EPA 608 Core Questions
- EPA 608 Type I Prep
- EPA 608 Type I Practice Test
- EPA 608 Type II Prep
- EPA 608 Type II Practice Test

LMS REFRIGERATION

- EPA 608 Core Certification Prep

EPA STUDY MATERIAL

- EPA 608 Study Book
(available via Local Supply House)

Resources

Key Competencies

By completion of this Learning Block, technicians should demonstrate competency in:

- | | | |
|--|---|---|
| ☐ EPA Refrigerant Regulations | ☐ Recovery Requirements | ☐ EPA Type I Certification Topics |
| ☐ Ozone Depletion & Envir. Responsibility | ☐ Leak Prevention & Compliance | ☐ EPA Type II Certification Topics |
| ☐ Refrigerant Safety & Handling | ☐ Refrigerant Cylinders & Identification | ☐ EPA Certification Exam Readiness |

Competencies

Mastery

EPA 608 Certification

Complete the **EPA 608 Certification** process by successfully passing the certification exam through an EPA-approved testing organization.

- Register for and complete the EPA 608 Certification Exam.
- Retain a copy of your EPA Certification Card.
- Return to the DRW platform.
- Upload your EPA Certification Card for Supervisor verification and documentation.